

# Oil Field Environmental Incident Summary

**Incident:** 20150918092539      **Date/Time of Notice:** 09/18/2015 09:25

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** EN-WEYRAUCH C-154-93- 2932H-1

**Field Name:** ROBINSON LAKE

**Well File #:** 20649

**Date Incident:** 9/17/2015      **Time Incident:** 11:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 93

**Sec:** 20

**Qtr:**

**Location Description:**

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW, Suite 20  
HOUSTON, TX 77010

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2000 Feet

**Distance Nearest Water Well:** 2000 Feet

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5.4	Barrels				

**Description of Other Released Contaminant:**

Emulsion

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There is no immediate risk to report at this time.

**Areal Extent:**

The areal extent was not able to be determined but all of the released fluid remained onsite.

**Potential Environmental Impacts:**

All of the released fluid remained onsite. There are no potential environmental impacts to report at this time.

**Action Taken or Planned:**

The Hess control room was immediately notified by Hess EHS. A new North Dakota One Call was initiated. The contaminated soil and gravel will be cleaned up and disposed of.

**Wastes Disposal Location:** The recovered waste will be taken to an approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 9/21/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pipeline leak, remained on location according to the report. NDIC retains oversight.